



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor


Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

July 11, 1995

TO: Minerals File

FROM: Tom Munson, Reclamation Hydrologist 

RE: Site Inspection, Wilden Flourspar Co., Lost Sheep Mine, S/023/029, Juab County, Utah

Date of Inspection: May 16, 1995
Time of Inspection: 4:00 PM - 5:00PM
Conditions: Sunny
Participants: Lynn Kunzler, Wayne Hedberg, Tom Munson - DOGM - Mike Provstguard - Wilden Flourspar Co.

On May 16, 1995 we visited the flourspar mine and discussed the current mining plans with Mr. Mike Provstguard. He informed us of the enlargement of the mine by creating another shaft adjacent and connected to the one which currently exists. The Disturbance will not be enlarged considerably because most of the mining will be done in the shaft area. The equipment which exists on site and is currently being used, consisted of four dump trucks, some conveyors, a derrick, an old bus, an old trailer, several tin sheds, a small cabin, a front end loader, and a dozer. There is miscellaneous scrap metal and conveyor belt.

The site looked as if the operator had good housekeeping habits but no reclamation of any areas had occurred.

jb
S023029.ins



LOST SHEEP MINE

5/16/95 INSPECTION

W. HEDBERG, L. KUNZLER, T. MUNSON

TIME: 4PM - 5PM

S/023/029






EXISTING SHAFT TO BE CONNECTED
TO NEW
5/16/95
LOST SHEEP MINE
5/023/029




DUMP TRUCKS
+
LOADING AREA



MIKE PROUSTGARD
+
LOADING AREA

5/16/95
LOST SHEEP MINE
5/623/029



5/022/629

LOST SHEEP MINE

5/16/95



NEW SHAFT NOT
DEVELOPED AS OF
7/12/95




WILDEN FLOURSPAR CO.
LOST SHEEP 5/023/029


ACCESS ROAD




ROCKPILES




ACCESS ROAD
LOST SHEEP



WILDEN FLOUR SPARE CO.
LOST SHEEP S/623/029



main mine site



S 023/029 5/16/95
 AOST SHEEP MINE
 SITE INSPECTION